

CROSS-CUTTING ON THE VARIETY SAW

- ① Mark stock
- ② Remove rip fence
- ③ Square blade to table and set blade height
- ④ Square **mitre guage**
- ⑤ Install mitre guage in slot and place stock against mitre guage
 - ☞ good edge against mitre guage
 - ☞ good face on table
- ⑥ Hold stock against the mitre guage with both hands and push stock through blade until stock is clear of guard
- ⑦ Turn machine off and wait until blade has stopped moving before removing waste from blade area.
 - ☞ for multiple crosscuts, waste should be cleared from blade area with a push stick so that pieces are not thrown at operator