Day 25

CUTTING A MORTISE BY MACHINE

- Mark out all the **mortises** to be cut.
- 2 Check to see if **hollow chisel** is square to fence and table and adjust if necessary.
- **3** Set mortiser depth.
- 4 Clamp stock in mortiser vise.
 - be sure stock is secure
 - be sure good face is against fence
 - be sure of enough table travel
- Turn machine on and begin cutting taking many small cuts.
 - be sure to lift chisel completely out of stock before moving to next cut.
- **6** Turn machine off when finished.